## **WARNINGS-SHOTSHELL**

No data shown in the lead shot data section should be used with steel, bismuth, or other non-toxic shot.

Never substitute components (except where indicated) when loading shotshells using the data herein. Substitution of different components could cause excessive or dangerous pressures, which could damage or destroy your firearm, or cause serious personal injury, or even death to the user and/or bystanders.

After choosing an appropriate load, we recommend to weigh actual charges thrown by a bushing or charge bar. No bushing or charge bar throws the exact charge as listed in the bushing/charge bar charts. Such changes occur because of small tolerances in bushing sizes, tolerances in bulk density of powder, and the way each loader is mounted and operated. It is important to verify weights for safety and to ensure a proper load.